



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEX Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.:	<b>GB/ITS/QAR06.0004/08</b>	Page 1 of 2
QAR Free Ref. No.:	<b>G104573447</b>	Status: <b>Issued</b>
Details of change:	Surveillance Audit completed 2022-02-02	Date of issue: <b>2022-06-06</b>
Site(s) audited:	<b>SERVOMEX GROUP Limited.</b> Servomex Technical Centre Jarvis Brook East Sussex Crowborough, TN6 3FB <b>United Kingdom</b>	Valid until: <b>2024-04-14</b>  Audit date: <b>2022-06-06</b>
Issuing ExCB:	<b>ITS - Intertek Testing &amp; Certification Limited</b>	
Manufacturer:	<b>SERVOMEX GROUP Limited.</b> Servomex Technical Centre Jarvis Brook East Sussex Crowborough, TN6 3FB	
Location of Manufacturer:	<b>United Kingdom</b>	
Product information:	Analysers	
Protection concept:	<b>Ex i, Ex d, Ex e, Ex p, Ex n, Ex t, Ex op is</b>	
Related QARs:		
GB/ITS/QAR06.0004/00	GB/ITS/QAR06.0004/01	GB/ITS/QAR06.0004/02
GB/ITS/QAR06.0004/03	GB/ITS/QAR06.0004/04	GB/ITS/QAR06.0004/05
GB/ITS/QAR06.0004/06	GB/ITS/QAR06.0004/07	

Related Certificates (manual insertion)::

**IECEX BAS 04.0027X**  
**IECEX BAS 04.0051**  
**IECEX BAS 04.0052**

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEX BAS 06.0024 issue: 2	IECEX BAS 06.0024 issue: 3	IECEX BAS 06.0024 issue: 4
IECEX BAS 06.0024 issue: 5	IECEX BAS 06.0024 issue: 6	IECEX BAS 06.0030 issue: 1
IECEX BAS 06.0030 issue: 2	IECEX BAS 06.0030 issue: 3	IECEX BAS 06.0030 issue: 4
IECEX BAS 06.0030 issue: 5	IECEX BAS 06.0042X issue: 3	IECEX BAS 06.0042X issue: 4
IECEX BAS 06.0042X issue: 5	IECEX BAS 09.0029X issue: 0	IECEX BAS 09.0029X issue: 1
IECEX BAS 09.0029X issue: 2	IECEX BAS 09.0029X issue: 3	IECEX BAS 09.0029X issue: 4
IECEX BAS 09.0029X issue: 5	IECEX BAS 09.0029X issue: 6	IECEX BAS 10.0028X issue: 0
IECEX BAS 10.0038X issue: 0	IECEX BAS 10.0038X issue: 1	IECEX BAS 10.0038X issue: 2
IECEX BAS 10.0038X issue: 3	IECEX BAS 10.0038X issue: 4	IECEX BAS 10.0038X issue: 5
IECEX BAS 11.0128X issue: 0	IECEX BAS 12.0045X issue: 0	IECEX BAS 13.0137U issue: 0
IECEX BAS 13.0137U issue: 1	IECEX BAS 14.0092X issue: 0	IECEX BAS 14.0092X issue: 1
IECEX BAS 15.0112X issue: 0	IECEX BAS 15.0112X issue: 1	IECEX BAS 16.0094X issue: 0
IECEX BAS 16.0094X issue: 1	IECEX BAS 16.0094X issue: 2	IECEX CQM 13.0001X issue: 0
IECEX CSA 14.0052 issue: 0	IECEX ITS 12.0047X issue: 0	IECEX ITS 12.0047X issue: 1
IECEX ITS 12.0047X issue: 2	IECEX ITS 12.0047X issue: 3	IECEX ITS 19.0016U issue: 0
IECEX SIR 09.0136X issue: 0	IECEX SIR 09.0136X issue: 1	IECEX SIR 10.0007X issue: 0
IECEX SIR 10.0007X issue: 1	IECEX SIR 10.0007X issue: 2	IECEX SIR 10.0007X issue: 3
IECEX SIR 10.0007X issue: 4		



# IECEX Quality Assessment Report Summary

QAR Ref. No.:

**GB/ITS/QAR06.0004/08**

Page 2 of 2

Comments: